

ਦਫ਼ਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,ਪ੍ਰਾਂਤਕ ਉਪ ਮੁੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,

ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ,ਮੋਗਾ

Email: sdepsdmogapwdpb@gmail.com

ਵੱਲ,

Principal, Akal Academy Bakarwala.Disti,Moga.

ਨੰਬਰ 107 ਮਿਤੀ 29 05 2023

िल्यां :-

ਇਮਾਰਤ ਸੁਰਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਬਾਬਤ ਸਾਲ 2023-2024

ਹਵਾਲਾ :-

ਆਪ ਦਾ ਪੱਤਰ ਨੰ: AAB/414/2023 ਮਿਤੀ 03-04-2023

ਉਪਰੋਕਤ ਇਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਸਬੰਧਤ ਜੇ.ਈ. ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਸਾਲ 2023-24 ਲਈ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ ਹੈ।ਸਕੂਲ ਦੀ ਇਲਡਿੰਗ ਦਾ ਸੁਰਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਆਪ ਨੂੰ ਮਿਤੀ 31-03-2028 ਤੱਕ ਦਾ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਹੈ।ਅੱਗੇ ਤੋਂ ਹੇਠ ਲਿਖੀਆਂ ਹਦਾਇਤਾਂ ਵੱਲ ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇਂ :-

- । ਜੇਕਰ ਇਮਾਰਤ ਵਿਚ ਕੋਈ ਤਬਦੀਲੀ/ਵਧਾਇਆ ਜਾਂ ਘਟਾਇਆ ਜਾਂਦਾ ਹੈ ਤਾਂ ਕੰਮ ਕਿਸੇ ਤਕਨੀਕੀ ਇੰਜੀਨੀਅਰ ਦੀ ਦੇਖ ਰੇਖ ਵਿਚ ਹੀ ਕਰਵਾਇਆ ਜਾਵੇ,ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਨਿਮਨ ਹਸਤਾਖਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।
- 2 ਜੇਕਰ ਇਲਤਿੰਗ ਦੀਆਂ ਕੰਪਾਂ,ਨੀਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫਤ ਕਰਕੇ ਬੈਠ ਜਾਣ ਅਤੇ ਇਸ ਸੂਰਤ ਵਿਚ ਨਿਮਨ ਹਸਤਾਖ਼ਰ ਨੂੰ ਫੌਰੀ ਤੌਰ ਤੇ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿਚ ਲਿਆ ਜਾਵੇ ਜੀ।
- 3 ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੇਅਰ ਹਰ ਸਾਲ ਕਰਵਾਈ ਜਾਵੇ।ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਪੱਖੋਂ ਸੇਫਟੀ ਦੀ ਸਾਰੀ ਜਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਸੰਸਥਾ/ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।
- 4 ਉਕਤ ਸਕੂਲ ਵਿਚ ਲੱਗੇ ਅੱਗ ਬੁਝਾਊ ਯੰਤਰ ਸਬੰਧੀ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਹਰ ਸਾਲ ਸਬੰਧਤ ਦਫਤਰ ਤੋਂ ਲੈਣ ਦੀ ਜਿਮੇਵਾਰੀ ਆਪ ਦੇ ਸਕੂਲ/ਸੰਸਥਾ ਦੀ ਹੋਵੇਗੀ।
- 5 ਇਹ ਸਰਟੀਫਿਕੇਟ ਕਿਸੇ ਵੀ ਲੀਗਲ ਕੇਸਾਂ ਲਈ ਪ੍ਰਮਾਣਿਤ ਨਹੀਂ ਹੋਵੇਗਾ।
- 6 ਨਿਮਨ–ਹਸਤਾਖ਼ਰ ਉਕਤ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ 2023–2024 ਸਮੇਂ ਵੀ ਨਿਰੀਖ਼ਣ ਕਰ ਸਕਦੇ ਹਨ।ਨਿਰੀਖ਼ਣ ਦੌਰਾਨ ਕਿਸੇ ਕਿਸਮ ਦੀ ਕੋਈ ਅਣਗਹਿਲੀ ਪਾਈ ਗਈ ਤਾਂ ਬਿਨ੍ਹਾ ਕੋਈ ਨੋਟਿਸ ਦਿੱਤੇ ਜਾਰੀ ਬਿਲਡਿੰਗ ਸੋਫਟੀ ਸਰਟੀਫ਼ਿਕੇਟ ਰੱਦ ਕੀਤਾ ਜਾ ਸਕਦਾ ਹੈ।
- 7 ਡਾਇਰੈਕਟਰ ਜਰਨਲ ਸਕੂਲ ਸਿੱਖਿਆ ਵਿਭਾਗ ਪੰਜਾਬ ਸਟੇਟ ਪ੍ਰੋਜ਼ੈਕਟ ਸਰਵ ਸਿੱਖਿਆ ਅਭਿਆਨ ਦੇ ਪੱਤਰ ਨੰ: 75444 ਮਿਤੀ 06–11–2009 ਮੁਤਾਬਿਕ ਸਕੂਲ ਵਿਚ ਅੱਗ ਬੁਝਾਉਣ ਵਾਲੇ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿਚ ਹੱਥੇ ਜਾਣ ਕਿਸੇ ਵੀ ਅਣਸੁਖਾਂਵੀ ਦੁਰਘਟਨਾ ਦੀ ਸਾਰੀ ਜਿੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ

ਅਗਲੇ ਸਾਲ 2024–25 ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਕਰਾਉਣੀ ਯਕੀਨੀ ਬੁਣਾਈ ਜਾਵੇ।

ਨੱਧੀ/ਸ਼ਰਟੀਫਿਕੇਟ।

8

PRINCIPAL AKAL ACADEMY BAKARWAL (MOGA) ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪਾਂਤਕ ਉ<u>ਪ</u> ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ

MANAGER
AKAL ACADEMY
BAKARWAL (MOGA)

Ltr pb

Building Safety Report (PART-II)

NAME OF SCHOOL ;-Akal Academy Bakarwala (District- MOGA)

As per report of Sh, Jagsir Singh Junior Engineer on his visually inspection on dated 13-04-2023 the above mentioned School seems visually safe subject to the following observations an conditions.

- The parameters to check the stability and safety of building such as structural Design
 Architectural Drawings, Bearing capacity, Foundation details, Structural drawings,
 Technical Specifications, Test report of Material used and Quality control report are not
 available.
- In Case any addition, alteration. Expansion and modification to this building are required/to be done, regarding this, inspections of undersigned may be arranged and obtained a certification after the completion from the undersigned.
- 3. In the case of building is affected flood or if there is any settlement of walls Foundation of roof etc. immediately inspection of the undersigned arranged to check the stability and safety of the building.
- 4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- A separate certificate regarding Electrical works should be obtained from the competent Authority.
- 6. The owner of the building/Management is fully responsible regarding safety if the building from all angles in spite of this report.
- 7. This report is for the the covered area of School building **32442.79**. sft which is submitted by the school is building as per drawing.
- 8. The building of the school is constructed as brick masonry.
- 9. This report is not valid for legal purpose.
- 10. That the fee charges for the year 2023-2028 Rs. Fifty Thousand only With Merchant Reference No. 5764795 Dated 25-04-2023.
- 11. Fire safety Certificate is valid till 31.03-2024 and School will be responsible to get renewed fire safety Certificate within time limit.

As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal up to 31.03.2028 Subject to the above conditions.

Junior Enginee

PRINCIPAL AKAL ACADEMY BAKARWAL (MOGA) and Ulvisional Engineer, Provincial Sub Division.

FWD (688) Br Moga

AKAL ACADEMY BAKARWAL (MOGA) 14) Requirement for fire Protection Arrangements under NBC

Part -IV
(For Building height Less than 15metre)

(For Building height Less than 15metre)

(For Building height Less than 15metre)

(Yes / No

Yes / No

Weather house Real provided.

(Yes / No

Weather automatic sprinkler provided.

(Weather automatic sprinkler provided.

(Weather underground static water storage tank of Capacity 50,000Ltr.(It converted are excess 1600sqm)

Yes/ No

e) Weather over head tank of capacity 10,000 Ltr. Exists.(in case of house real) 20,000 Ltr.

f) Weather one electric and one diesel pump of 3 kg/ cum
Pressure of capacity 1620 LPM. One electric pump of
Capacity 180LPM exist near underground static tank.

g) Weather a pump 3 Kg/cum preasur & 450/500 LPM Exist near over head tank.

Yes/No

Yes/No

PRINCIPAL Scholsanademy BAKARWAL (MOGA)

PART -II (To be filled by the S.D.E for PWD (B&R) Department)

a) I have visited the above mentioned school on date 13-04-2023. And have been visually inspected it from all angles of safety and fined it fit for normal used as school buildings.

b) In case and addition / alteration of expansion and modifications to this building is to be carried out the same be carried out under the supervision of a qualification Engineer and this certificate may be re-obtained after the completion from the undersigned.

c) In case the building is affected by food, or if there is settlement of walls/ foundation of sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.

d) This building can be safety occupied for normal used upto (indicate upto which it can be used) Walid up la 31-03-2028

PRINCIPAL AKAL ACADEMY BAKARWAL (MOGA)

Seb Drotslonal Engineer, Provincial Sub Elvision, PWD (ESK) Br. Maga.

> MANAGER AKAL ACADEMY BAKARWAL (MOGA)